

Recorded
8-7-64 emj.

FEDERAL BUREAU OF INVESTIGATION
UNITED STATES DEPARTMENT OF JUSTICE

Laboratory Work Sheet

LAB FILE

Re: LEE HARVEY OSWALD, aka
19 - R - CUBA

File # 105-82555-4668X
Lab. # D-455927 HO

PC 81827 CF, BX

Examination requested by: President's Commission (7-7-64)

Examination requested: Photographic ^{Spectrographic} Firearms

Date received: 8-6-64

Result of Examination:

Examination by: Shanesfelt

8/10 R Frazer
31° from horizontal

Use C# in lower

C321

Q607 Piece of Curbing

Specimens submitted for examination

Barly discernable
smoothing off - no
groove or visible
end dep. No cup part.
from Q - not pointed
bullet.

Request for location and examination of mark on curbing at assassination site

Curb - minor disturbance at L to edge.

If lead - antimony present it could
have originated from the core portion of a metal
jacketed bullet such as C1,2,3, a automobile
wheel balancing weight or some other source
of lead. The absence of copper - alloy bullet jackets
renders possible the possibility that the waste was

2-FBI, Dallas (100-10461) made by an unmetallated bullet
unmetallated bullet. Further the damage to the curbing
would have been much more severe extensive if a rifle
bullet such as C1,2,3 had struck the curb without penetrating

O O
D-455827 HO
PC 81827 CT, BX

curling looking piece of curbing was removed on 8-5-64 and is still at the FBI Lab.
Designated C-32-1 by the Laboratory.

Small foreign metal smears were found to be adhering to the curbing section at an area which bears a mark. These metal smears were analyzed spectrographically determined to be essentially lead with a trace of antimony. No copper was found.

The lead could have originated from a lead bullet, the lead core of a metal jacketed bullet such as the type of bullet recovered from Governor E. G. Tammie-Carrano cartridges or from some other source having the same composition.

The absence of copper precludes the possibility that the mark on the curbing section was made by an uninitiated full jacket military type full metal-jacketed bullet such as the bullet recovered from Governor Stachels, etc., for the bullet jacket or bullets represented by the jacket fragments, C-2 and C-3, found in the President's limousine. Further, the damage to the curbing would have been much more extensive if a rifle bullet had struck the curbing without first having struck some other object.

Recorded
8-7-64 emf.

FEDERAL BUREAU OF INVESTIGATION
UNITED STATES DEPARTMENT OF JUSTICE

Laboratory Work Sheet

LAB FILE

Re: LEE HARVEY OSWALD, aka
19 - R - CUBA

File # 105-82555-4668X
Lab. # D-455927 HO
PC 81827 CF, Bt

Examination requested by: President's Commission (7-7-64)

Examination requested: Photographic Silhouettes
Firearms

Date received: 8-6-64

Result of Examination:

Examination by: Shoneyfelt

8/10 R. Frazer

33° from horizontal

Use C# in lower

C321

Q607 Piece of curbing

Specimen submitted for examination

Barely discernably
smoothing off - no
groove or visible
end dep. No impact
from Q - not pointed
bullet.

Request for location and examination of mark on curbing at assassination
site

Curb - minor disturbance at C to edge.

If lead casting present it could
have originated from the core portion of a metal
jacketed bullet such as C1,2,3, a automobile
wheel balancing weight or some other source
of lead. The absence of copper-alloy bullet jacket
residue precludes the possibility that the mark was
made by an unjacketed bullet.

2-FBI, Dallas (100-10461) made by an unjacketed bullet.
would have been much more severe if a rifle
bullet such as C1,2,3 had struck the curb without penetrating

O O
D-45582-7110
PC 81827 CF, Bd

inflicting the injury the piece of curbing was removed on 8.5.64 and trail at the FBI Lab.
Designated 321 by the FBI Laboratory.

Small foreign metal smears were found in adhering to the curbing section at an area which bears a mark. These metal smears were analyzed spectrographically determined to be essentially lead with a trace of antimony. No copper was found.

The lead could have originated from a lead bullet, the lead core of a metal jacketed bullet such as the type of bullet recovered from Governor Wallace or from some other source of lead, or from some other source having the same composition.

The absence of copper precludes the possibility that the mark on the curbing section was made by an unjacketed full jacket-military type full metal-jacketed bullet such as the bullet recovered from Governor Wallace, or the bullet jacket or bullets represented by the jacket fragments, C2 and C3, found in the President's limousine. Further, the damage to the curbing would have been much more extensive if a rifle bullet had struck the curbing without first having struck some other object.

7-2
Recorded
8-7-64 encl.

FEDERAL BUREAU OF INVESTIGATION
UNITED STATES DEPARTMENT OF JUSTICE

Laboratory Work Sheet

LAB FILE

Re: LEE HARVEY OSWALD, aka
LS - R - CUSA

File # 105-82555-4668X
Lab. # D-455927 HO

Examination requested by: President's Commission (7-7-64)

Examination requested: Photo-graphic-microscopic ^{Specimens at this} Date received: 8-6-64
Firearms

Result of Examination:

Examination by: Shane

Mark on curb is 23' 4" from Triple underpass.
A direct shot from 6th floor window TSBD would
cross over pres in center of Elm St at about 18' elevation
& at Zapruder frame 410. 97 frames after 313 or
5.3 sec @ 18.3 f.p.s.

Specimens submitted for examination

Q609

Request for location and examination of mark on curbing at assassination site

At frame 410 Mrs K is back in car &
Hill is midway between bumper & pres.

Curbing removed - Mark made by object
traveling in general direction away from TSBD.

11:12 P.M.
11:11 A.M.

8-11-64 / S

2-FBI, Dallas (100-10461)

84 AUG 27 1964

105-82555-4668X