justice from the 101

and Brearm, food mark a Burena of Criminal

ad past president of the aminers and currently ber of the International t the Iowa Department

at the facilities of the Identification Section, nel and working closely Wilson, senior firearms Vashington, D.C., a pov, which he established,

Association of Firearm cived the association's -year tenure with the awarded over 30 comperformance of duty. y police photographer

Department's Photo-

nce and attempt to an-

fired from the alleged

in the rifle fired in that

loaded into the rifle ober?

vpe and brand as the ilitary-type cartridges

· same type and brand box commercial-type

ing and the cartridge .urtridge?

· Peters cartridge box tay's rifle or any other

he surface of the win-

ktie, and suitcoat prog else?

Iso pursue other areas

Proceedaries and signifiment 4 2 4 4 5 5

As noted, The panel conducted its examination at the Pirearum Identification Section of the Washington, D.C., Metropolitan Police Department. These facilities were conveniently located to the National Archives and the select committee's offices, and were made available by Police Chief Maurice J. Cullinane and Firearms Section Supervisor George R. Wilson.

(51) The panel members met initially on August 24, 1977, with the committee and the technical assistant from the Metropolitan Police Department's Firearms Laboratory. At that time, the following examination procedures were adopted:

(52) Each panel member would independently examine and compare under a microscope the bullet recovered from Dr. King, the cartridge case found in the rifle, the bullets and cartridges test-fired by the panel (see below) and the bullets and cartridge cases received from the FBI and listed as having been fired in the rifle. (53) The panel would jointly conduct microscopical, chemical and

visual examinations of all other evidence, as well as of the rifle, bullets and cartridges test-fired in it (see below). Each examiner would keep individual worksheets and notes. (54)

Among the specific tests to be conducted were: (55)

Comparison of the bullets test-fired by the panel from the rifle (see below), and with bullets received from the FBI and listed as having been fired from the rifle.

(56) Comparison of the cartridge case found in the rifle with cartridge cases test-fired by the panel in the rifle, and with cartridge cases received from the FBI and listed as having been fired in the rifle.

(57) Comparison of the exterior of the rifle with an impression in the surface of the windowsill.

(58) Before discussing his findings with other panel members, each examiner would submit his individual notes and worksheets and a final report to the technical assistant.

(59) On completion of the individual examinations, the panel would meet to discuss the findings of each member, reexamine the evidence as necessary, and then prepare a final, joint report, to be submitted to the select committe.

(60) Members would not be shown the results of the earlier FBI tests. The FBI reports were, however, to be reviewed by the technical

(61) After considering the results of the FBI's neutron activation analysis, the committee decided not to conduct further examinations of this type. Because the elemental composition of the five Peters cartridge box commercial-type cartridges.differed, they could not be used as standards of comparison with the bullet recovered from Dr.

(62) As noted, the panel was to conduct visual and microscopical examinations, as necessary, on each item of evidence. A summary of general principles follows:

(63) A cartridge, or round of ammunition, consists of a cartridge case, primer, powder, and bullet. The primer contains a detonable mixture and fits into the base of the cartridge case, which contains powder. The bullet, constructed of lead or a lead core encased in a



stronger metal jacket, fits into the mouth of the cartridge case. A bullet is fired by placing the cartridge in the chamber of the firearm. The cartridge base rests against a solid support, called a breech or bolt face. When the trigger is pulled, the firing pin strikes the primer, igniting the detonable mixture, which in turn ignites the powder in the cartridge case. The combustion propels the bullet through the barrel.

(64) The bore (inside of the barrel) of modern firearms is rifled with spiral grooves in it to give bullets fired through it a spinning motion for flight stability. The raised portions between the grooves are called lands. The number, width and direction of twist of the lands and grooves are called the class characteristics of a barrel.

(65) In addition to the class characteristics, the components of every firearm, such as the barrel, firingpin and breech face, bear distinctive microscopic characteristics. While the class characteristics are common to all firearms of a given model and manufacture, an individual firearm's microscopic characteristics differ from all other firearms, regardless of model or manufacture. These distinctive markings, usually referred to as individual identifying characteristics, are produced initially by the manufacturing tools, which change microscopically during operation and vary from one firearm to another. Further individual identifying characteristics may be produced as the firearm is used, during its disuse, and as a consequence of maintenance or the lack of it.

(66) When a firearm is discharged, the individual identifying characteristics of its barrel, as well as its class characteristics, are engraved on the bearing surface of the bullet. The individual identifying characteristics of the firingpin and breech or bolt face are impressed on the base or primer of the cartridge case at the time of firing.

(67) Using a comparison miscroscope, an expert can compare the markings with those produced on a similar cartridge test-fired in the same firearm. If the patterns of the microscopic markings are sufficiently similar, it can be concluded that both cartridge cases were fired in the same firearm.

(68) Microscopical examination of other firearm components and the markings they produce may also demonstrate such things as whether a cartridge was ever loaded into a particular firearm or was loaded into a firearm more than once. It is also possible, through comparative miscroscopical examinations, to determine whether two bullets were fired from the same firearm.

(69) The committee obtained the firearms evidence from the Criminal Court of Shelby County, Tenn., on March 11, 1977; the autopsy photographs came from the office of the Shelby County medical examiner. All items of evidence were inventoried before and after being transferred to and from the police laboratory in Washington in August and September. Deputy Clerk of the Criminal Court of Shelby County, Charles Koster, came to Washington on August 24, 1977, to oversee the transfer of the firearms evidence to the police laboratory and to review security precautions generally. The evidence was secured in a safe in the laboratory; a log was maintained to record when the evidence was removed for examination.

(70) The bullets and cartridge cases test-fired by the FBI from the rifle were obtained for the committee from Special Agent Cort-

landt Cunningham by George R. Wils (71) The examination (11) The cauncilla ber 23 to 27, 1978. (72) Two Ameri model K1453, seri candescent lighting pieces and objective and 40X, the other ((73) American O lens of 0.7- to 8-pov EPOI "Elec (74)(75)Mico model (76) Slocomb "Sr 77 Brown and S (78)Marshall's re 79) Sodium rhod 80) Horizontal w (81)Horizontal c (82) .30-06 Sprir cartridges of Rem cartridges test fired No designation was loaded and unloaded (83) This ammuni stock. It was similar rifle and to the five (84) The panel con Springfield caliber (water recovery tank nose portion Subrecovery and cartridge . (85) Additional ... fired, for loading and ual identifying chara (86) At the time c mounted on the rifle 1968, noted that ceiv. ' the rifle the test in d the rifle, as curacy using the sigh the dia ance from what cording to its report d

approximately 3 inchaim."(14) The reporaligned when the rifle before the FBI labors the distortion found in to test the rifle for acci

42-635 0 - 79 - 5

tridge case, A of the firearm. ed a breech or kes the primer, the powder in I through the

carms is rifled i it a spinning en the grooves ist of the lands rrel.

onents of every war distinctive istics are com-, an individual er firearms, rerkings, usually are produced microscopically er. Further inas the firearm stenance or the

al identifying eristics, are enual identifying · are impressed of firing. a compare the test-fired in the

kings are sufficases were fired unponents and such things as

firearm-or was , through comwhether two

nce from the 1, 1977; the auounty medical fore and after Washington in 'ourt of Shelby ust 24, 1977, to lice laboratory idence was seto record when

FBI from the 1 Agent Cortlandt Cunningham, Chief of the FBI Firearms Identification Unit, by George R. Wilson.

(71)The examinations were conducted August 24 to 27 and Septem-

ber 23 to 27, 1978. The following equipment was used: (72) Two American Optical forensic comparison microscopes, model K1453, serial Nos. 328 and 277, with fluorescent and incandescent lighting, fiber optics, photographic unit, and 10X eye-pieces and objectives. One had a combined magnification of 12X, 20X, and 40X, the other of 20X, 40X, and 80X.

American Optical low-power binocular microscope with zoom (73)lens of 0.7- to 3-power eyepieces. (74) EPOI "Electromike" measuring projector, model MP6.

75)

Mico model 5100 balance, with a 1,000-grain capacity. (76)

Slocomb "Speedmike" direct readout micrometer. Brown and Sharpe stage micrometer for air gap measuring. (77)78

Marshall's reagent (Griess test). (79)

Sodium rhodizonate reagent. (80)

Horizontal water recovery tank.

 (81) Horizontal cotton waste recovery box.
(82) .30-06 Springfield caliber, 150-grain, soft-point, jacketed cartridges of Remington-Peters manufacture, index 3083. Those cartridges test fired by the panel were designated panel T-1 to T-12. No designation was made for the unfired cartridges which the panel loaded and unloaded in the rifle.

This ammunition was supplied from the police department's (83)stock. It was similar to the expended cartridge case found in the Q-2 rifle and to the five commercial-type cartridges found in the Peters cartridge box.

The panel conducted 12 test firings of the rifle using the .30-06 (84)Springfield caliber cartridges. The first test shots were fired into a water recovery tank. This resulted in excessive expansion of the bullets' nose portion. Subsequent shots were fired into a horizontal cotton waste recovery box, which left the bullets more intact. All test-fired bullets and cartridge cases were used for comparison.

Additional .30-06 Springfield caliber cartridges were used, un-(85)fired, for loading and unloading in the rifle to obtain class and individual identifying characteristics produced in that process. (86)

At the time of the panel's examination, the telescopic sight mounted on the rifle was set at "3X." An FBI report dated April 17, 1968, noted that the sight was set at "64/2X" when the laboratory received the rifle the day after the assassination. (13) The laboratory had test fired the rifle, as received, on April 5, 1968, to determine its ac-curacy using the sight. Groups of three shots were fired at 205 feet, the distance from which Dr. King was believed to have been shot. According to its report dated April 14, 1968, "the center of the groups was approximately 3 inches to the right and only slightly below the line of aim."(14) The report noted that the sight could have become misaligned when the rifle was abandoned or during subsequent handling before the FBI laboratory received it, and that this could have caused the distortion found in the tests. For this reason, the panel decided not to test the rifle for accuracy using the telescopic sight.

42-636 0 - 79 - 5

(87) The panel's examination required a total of 257 man-hours. The panel submitted a final joint report of its findings on October 28, 1977. Evidence examined

The evidence examined was:

(89) Exhibit Q1 -- One two-piece gold, brown, and black box, la-beled "Browning Mauser," found along with other evidence at Canipe's (89) Amusement Co.² (See figure 1.)

Exhibit Q2-One .30-06 Springfield caliber pump-action rifle, (92)Remington Gamemaster model 760, serial No. 461476, found at Canipe's Amusement Co. Attached is a Redfield 2X to 7X variable telescopic sight, serial No. A17350, and a Weaver sight mount.⁸ (See figs. 2A and 2B.)

(96) Exhibit Q3 .- One expended commercial-type .30-06 Springfield caliber cartridge case of Remington-Peters manufacture, found in the Q2 rifle. (See figs. 3A and 3B.)

(97) Exhibit Q4-Q12.-Q4-Q8-Component parts of the five commercial-type .30-06 Springfield caliber cartridges of Remington-Peters manufacture, with 150-grain, jacketed, pointed soft-point bullets, found at Canipe's Amusement Co. in the Peters cartridge box. (See fig. 4A.) Q0-Q12-Four military-type .30-06 Springfield caliber cartridges of Remington Arms Co. manufacture, with full metal-jacketed bullets, found at Canipes Amusement Co. in the Peters cartridge box. (See figs. 4B and 4C. Cartridge box—One Peters .30-06 Springfield caliber cartridge box, found at Canipes Amusement Co. (See fig. 4 n.) (98) Exhibit Q64.-Three fragments ' from the damaged jacketed bullet removed from Dr. King. They were : (1) the base portion of the bullet jacket, weighing 30.9 grains; (2) a jacket fragment weighing 6.7 grains; (3) a portion of the lead core material, weighing 26.8 grains. The combined total weight was 64.4 grains. (See fig. 5.)

(99) Exhibit Q71.-A piece of wooden board with a tag marked, "part of windowsill from window of bathroom on east side of apartment house, second floor (north wing), over 418-4221/2 South Main Street, Memphis, Tenn." It was about 31% inches long, 5 inches wide and 1 inch thick, highly weathered, with a considerable quantity of white paint on one edge. It had a shallow, elongated indentation about

¹The "Q" numbers were designated by the FBI. ⁸The punct found it to be in poor condition, held together with masking, transparent, and orange tape. It was wrapped in white twine, with a tag marked "James Earl Ray State No. 3085 and 3487." This box was originally intended as a shipping container for a Browning brand rifle.

"The panel found the rifle to be in good operating condition. The trigger pull was measured at 4% pounds, well within the manufacturer's specifications of 3% to 6% pounds. The magazine was a detachable box-type with a four-cartridge capacity. The barrel was rifled with six lands and six grooves, right twist. An examination of the rifle barrel revealed a residue in the bore which the

panel believed should be removed prior to test firing. This was done with a dry cloth patch pushed through the barrel. A red-colored substance was found on the front of and inside the magazine

where the operating rod screws into the receiver. Pursuant to the panel's request, the Remington Arms Co. identified it for the record as most probably "Loktite," a red-colored cement used by the Remington Arms Co. to secure certain threaded connections. (15)

'The bullet was recovered intact from Dr. King's body. As a result of subse-quent handling, the bullet has since fragmented into three pieces.

five-sixteenths inch long on t 4 inches from the painted ed (101) Exhibit Q76.—One shirt by Arrow and a pill moved from the shirt by the (102) Exhibit Q77.-One laine and a pill box contain: the tie by the FBI for analys (108) Exhibit Q78.—One containing a small piece of (analysis. (See fig. 9.) (104) FBI laboratory te.

mercial-type .30-06 Spring Remington-Peters manufa cartridge cases, all fired in t (105) Autopsy photograz

FIND NG8 AND CON

(106) The findings and c House Select Committee on by the panel members. The and conclusions.

Was the Q64 bullet fired fro (107) The Q64 bullet had damaged because of impac effects from penetration we Q64 bullet fragments (fig. ! tion of the jacket showed c grooves and six lands, right (108) Each panel member the Q64 bullet, the four bu the 12 bullets test-fired by class characteristics, all m bullets. (See fig. 11.) On t identifying characteristics, between the Q64 bullet and ferences were found. The I eliminate the Q64 bullet as (109)The panel noted the positively identified with a or more factors:

- -Damage to the bullet;
- -Variations in the hardr -Variations in gas press
- tridge to another;
- Natural variations caus ing from the high veloc barrel.

(110) When the bullets te Q2 rifle were compared mics tion among the individual i not be identified with each o

:57 man-hours. The in October 28, 1977.

and black box, lavidence at Canipe's

pump-action rifle, 5, found at Canipe's variable telescopic unt.[#] (See figs. 2A

c.30-06 Springfield acture, found in the

ts of the five com-Remington-Peters soft-point bullets, artridge box. (See ingfield caliber carfull metal-jacketed eters cartridge box. .30-06 Springfield the Co. (See fig. 4 n.) damaged jacketed base portion of the fragment weighing rial, weighing 26.8 (See fig. 5.)

with a tag marked, east side of apart-4221/2 South Main long, 5 inches wide lerable quantity of d indentation about

gether with masking, ine, with a tag marked originally intended as

ition. The trigger pull r's specifications of 3½ with a four-cartridge oves, right twist. in the bore which the a was done with a dry

d inside the magazine to the panel's request, st probably "Loktite," ccure certain threaded

As a result of subseleces. five-sixteenths inch long on the top surface midway along its length and 4 inches from the painted edge. (See figs. 6A and 6B.)

width?

(101) Exhibit Q76.—One white, men's long-sleeved button-down shirt by Arrow and a pill box containing a small piece of cloth removed from the shirt by the FBI for analysis. (See figs. 7A and 7B.) (102) Exhibit Q77.—One gold, brown and black necktie by Superlaine and a pill box containing two small pieces of cloth removed from the tie by the FBI for analysis. (See fig. 8.)

(103) Exhibit Q78.—One black suit coat by Petrocelli and a pill box containing a small piece of cloth removed from the coat by the FBI for analysis. (See fig. 9.)

(104) FBI laboratory test-fired cartridges.—Four deformed commercial-type .30-06 Springfield caliber jacketed softpoint bullets of Remington-Peters manufacture and two .30-06 Springfield caliber cartridge cases, all fired in the rifle by the FBI.

(105) Autopsy photographs.-Autopsy photographs of Dr. King.

FINDINGS AND CONCLUSIONS OF THE FIREARMS PANEL

(106) The findings and conclusions were prepared by staff of the House Select Committee on Assassinations based on material submitted by the panel members. The panel has read and accepts those findings and conclusions.

Was the Q64 bullet fired from the Q2 rifle?

(107) The Q64 bullet had been substantially distorted and generally damaged because of impact and penetration into Dr. King. Wiping effects from penetration were also noted. (See fig. 10.) Of the three Q64 bullet fragments (fig. 5), the panel found that only the base portion of the jacket showed class characteristics, which consisted of six grooves and six lands, right twist.

(108) Each panel member made a total of 81 comparisons between the Q64 bullet, the four bullets previously test-fired by the FBI, and the 12 bullets test-fired by the panel in the Q2 rifle. With respect to class characteristics, all members found correspondence among all bullets. (See fig. 11.) On the other hand, with respect to individual identifying characteristics, no significant correspondence was found between the Q64 bullet and the test bullets; conversely, no gross differences were found. The panel was unable positively to identify or eliminate the Q64 bullet as having been fired from the Q2 rifle.

(109) The panel noted that it is not unusual that a bullet cannot be positively identified with a particular rifle. This can result from one or more factors:

-Damage to the bullet;

- -Variations in the hardness of the bullet's metal;
- -Variations in gas pressures created during firing from one car-
- -Natural variations caused by the intense heat and friction resulting from the high velocity of the bullet as it is driven through the barrel.

(110) When the bullets test-fired by the FBI and the panel in the Q2 rifle were compared microscopically, the panel found so much varition among the individual identifying characteristics that most could not be identified with each other. (111) The panel concluded that the Q2 rifle inconsistently engraves individual identifying characteristics on successively fired bullets.

Was the Q3 cartridge case fired in the Q2 rifle?

(112) The Q3 expended cartridge case was compared microscopically with the two cartridge cases test-fired by the FBI and the 12 cartridge cases test-fired by the panel. The panel found correspondence among the individual identifying characteristics produced by the firing pin and bolt face. (See figs. 12 (bolt face and extractor of the Q2 rifle), 13 (bolt face impressions), 14 (extractor impressions), 15 (chamber impressions), 16 (bolt locking lugs of the Q2 rifle), and 17 (bolt locking lug impressions)). The panel concluded that the Q3 cartridge case was fired in the Q2 rifle.

Was the Q3 cartridge case loaded into the Q2 rifle through the magazine or directly into the chamber?

(113) The panel identified bolt drag marks (longitudinal striations) on the Q3 cartridge case (see fig. 17), similar to those produced experimentally on the test-fired cartridge cases and unfired cartridges. The relative position of bolt drag marks to the extractor marks (see fig. 12) on the rim of the Q3 cartridge case, which were engraved by the extractor and the bolt locking lugs (fig. 16) of the Q2 rifle, was also similar.

Is the Q3 cartridge case the same type and brand as the cases of the Q4-Q8 or the Q9-Q12 cartridges?

(114) The headstamp on the base of the Q3 cartridge case ("R-P .30-06 SPRG" (see fig. 3B)) indicated to the panel that it is commercial-type Remington-Peters ammunition—the same as the Q4-Q8 cartridges (see fig. 4A). The headstamps on the Q9-Q12 cartridges ("R A 55" (see fig. 4C)) indicated to the panel that they were military-type Remington Arms ammunition, unlike the Q3 and Q4-Q8 cartridges.

Is the Q64 bullet the same type and brand as the bullet portion of the Q4-Q8 or the Q9-Q12 cartridges?

(115) The Q64 bullet and the bullet components of the Q4–Q12 cartridges are all .30 caliber. Examination of the bullet jacket and core material of the Q64 bullet revealed that the jacket was of the same design and caliber and had cannelures similar to those of the bullet components of the Q4–Q8 cartridges (fig. 4A). The Q64 and the Q4–Q8 bullet components are therefore the same type.

(116) There were differences in design between the Q64 and the full metal-jacketed bullets loaded into the Q9–Q12 cartridges (fig. 4B). The Q64 bullet is not the same type of bullet as those in the Q9–Q12 cartridges.

Are the Q64 bullet and the Q3 cartridge case components of the same cartridge?

(117) The panel concluded that the Q3 cartridge case and the Q64 bullet had the same physical characteristics as the case and bullet components of the Q4–Q8 cartridges and that Q64 and Q3 could therefore be components of the same cartridge. However, the panel noted that there is no scientific procedure available that allows a fired bullet to be related conclusively to an expended cartridge case.

Were any of the Q4-Q12 magazine of the Q2 rit

(118) Visual and microsc panel revealed no extracto they were ever loaded in or any other firearm.

(119) The panel did find Q4-Q8 cartridges similar puller. Because the cartri panel assumed that the FE for its examinations.

(120) The panel found a tractor grooves, on the sid tridges that differed signif the Q2 rifle leaves. The pan part of a disintegrating m eight-round clip of the t fig. 18.)

Did the Q2 rifle cause t) windowsill?

(121) The windowsill bo and chemically. The sodiu point on Q71 removed fra cating possible contaminat for nitrites from gunpow panel decided that nothing further testing.

(122) Evidence of class (indicate the type of object found.

(123) The panel conclud insufficient either for iden spect to the identation. (S

Was the damage to Dr. Ki. produced by a bullet, l

(124) The Q76 shirt we examined (figs. 7A and 7I front and on both sleeves. . removed from the back cc bits of material from the 1 the right collar stay were stained.

(125) The shirt had a la right point area of the col and microscopical examin burned gunpowder in this no gunpowder residue. Th lead particles at the perim (126) The Q77 tie was v amined (fig. 8). It was cor stently engraves fired bullets.

1 microscopically 1 the 12 cartridge pondence among by the firing pin 1 the Q2 rifle), 13 15 (chamber im-17 (bolt locking artridge case was

brough the maga-

udinal striations) produced experid cartridges. The narks (see fig. 12) yed by the extrac-, was also similar.

is the cases of the

ridge case ("R-P cel that it is comime as the Q4-Q8 29-Q12 cartridges at they were miliie Q3 and Q4-Q8

illet portion of the

ts of the Q4-Q12 llet jacket and core 4 was of the same those of the bullet c Q64 and the Q4-

re Q64 and the full rtridges (fig. 4B). ose in the Q9-Q12

onents of the same

c case and the Q64 he case and bullet ind Q3 could thereer, the panel noted illows a fired bullet case.

Were any of the Q4-Q12 cartridges ever loaded into the chamber or magazine of the Q2 rifle or any other freerm?

(118) Visual and microscopical examination of the cartridges by the panel revealed no extractor, ejector or other marks to indicate that they were ever loaded in the magazine or chamber of the Q2 rifle or any other firearm.

(119) The panel did find marks within the extractor grooves of the Q4-Q8 cartridges similar to those made by an inertia-type bullet puller. Because the cartridges were originally recovered intact, the panel assumed that the FBI laboratory had taken the cartridges apart for its examinations.

(120) The panel found a series of marks and striations in the extractor grooves, on the sides and across the bases of the Q9-Q12 cartridges that differed significantly from the marks and striations that the Q2 rifle leaves. The panel concluded that these cartridges once were part of a disintegrating machinegun link belt or were contained in an eight-round clip of the type used with the Garand M1 rifle. (See fig. 18.)

Did the Q2 rifle cause the indentation on the surface of the Q71 windowsill?

(121) The windowsill board was examined visually, microscopically and chemically. The sodium rhodizonate test for lead, conducted at a point on Q71 removed from the impression area, was positive, indicating possible contamination from lead in the paint. The Griess test for nitrites from gunpowder residues yielded negative results. The punel decided that nothing of significant value would be obtained by further testing.

(122) Evidence of class characteristics (size and form) which could indicate the type of object making the indentation were likewise not found.

(123) The panel concluded that class and other characteristics were insufficient either for identifying or eliminating the Q2 rifle with respect to the identation. (See figs. 6A and 6B.)

Was the damage to Dr. King's Q76 shirt, Q77 necktie and Q78 suit coat produced by a bullet, bullet fragments or something else?

(124) The Q76 shirt was visually, microscopically and chemically examined (figs. 7A and 7B). It has been cut across the left and right front and on both sleeves. A small rectangular bit of material had been removed from the back collar area, as well as two small rectangular bits of material from the left cuff area. The collar button and part of the right collar stay were-missing. The shirt was extensively bloodstained.

(125) The shirt had a large, elongated hole of irregular shape in the right point area of the collar, extending below the collar line. Visual and microscopical examination revealed no partially burned or unburned gunpowder in this area. The Griess test for nitrites indicated no gunpowder residue. The sodium rhodizonate test for lead showed lead particles at the perimeter of the hole in the right collar area.

(126) The Q77 tie was visually, microscopically and chemically examined (fig. 8). It was completely severed next to the right side of the knot. A small bit of material had been cut from the rear of the neck band and two small bits from the inside lining.

(127) Visual and microscopical examination revealed no unburned or partially burned gunpowder particles in the severed area. The Griess test for nitrites was negative. The sodium rhodizonate test for lead was positive on the light-colored strand of lining protruding from the severed edge of the tie.

(128) The Q78 suit coat was visually, microscopically and chemically examined (fig. 9). It had been cut on the right sleeve and across the right chest. Small bits of material had been cut from the right upper sleeve area and the inner lining. The coat was extensively bloodstained. The upper right lapel area shows a series of irregular, tear-like holes in the outer layer of cloth. No penetration of the interfacing of the lapel was noted.

(129) Visual and microscopical examination revealed no unburned or partially burned gunpowder particles. The Griess test for nitrites was negative. Sodium rhodizonate testing revealed several areas with lead particles around the damaged right lapel area.

(130) Based on the visual, microscopical and chemical examinations of the clothing, the examination of the autopsy photographs of Dr. King, and considering the relative position of the garments when worn in the usual manner, the panel concluded that all damage to the Q76 shirt, Q77 necktie and Q78 jacket was consistent with the damage that would be caused by a high velocity bullet which fragmented on impact, and by the resultant secondary missiles such as bone and teeth fragments. The absence of gunpowder residues indicates that a firearm was not discharged in close proximity to the garments.

Summary of the findings

(131) Every effort was made by the firearms panel to identify or eliminate the Q64 bullet as having been fired from the Q2 rifle. The panel conducted numerous microscopical comparisons among bullets test-fired from the Q2 rifle by the panel and by the FBI. Not only could the Q64 bullet not be identified or eliminated through comparisons with test-fired bullets, but the test-fired bullets could not, in a majority of cases, be identified with one another, although they are known to have been fired from the same rifle.

(132) The panel found that the Q2 rifle, when the type of high velocity ammunition that was recovered in this case was used, did not produce similar individual identifying characteristics with any degree of consistency on bullets fired through it. Because of this situation, the panel could not identify or eliminate the Q64 bullet as having been fired from the Q2 rifle.

(133) The panel was able to determine, based on visual and microscopical examination, that the Q64 bullet is of the same type as the bullet portions of the Q4-Q8 cartridges. Thus, Q64 is the deformed bullet portion of a commercial-type .30-06 Springfield caliber cartridge of Remington-Peters manufacture and is unlike the bullet portions of the Q9-Q12 Remington Arms cartridges, which are militarytype.

(134) The panel determined that the Q3 cartridge case was fired in the Q2 rifle and had most probably been loaded into that rifle through the magazine rather than directly into the chamber. Further, the Q4-

Q12 cartridges possess no loaded into the magazine o The Q9-Q12 cartridges do 1 been loaded into disintegrai round clip for the M1 Gara (135) The panel finds the the Q4-Q8 cartridges are would normally be contain There is, however, no methcartridge case and the Q64 in the same box as the Q4-G (136) Spectrographic an of the Q64 bullet and the b ducted for purposes of ele cause of variation among t (137) The panel found th the Q77 necktie and the Q78 by a high-velocity bullet f secondary missiles such as b revealed particles of lead t ing, but no gunpowder resid (138) The panel found r pression area of the Q71 v eliminate the Q2 rifle as ha the presence of lead was p were negated by the lead-be analysis for the presence o negative results. The panel the possibility that a rifle ' windowsill.

(139) The results of the Q76-Q78 clothing and the (those of the FBI. There is performed any chemical and

of the neck

no unburned ed area. The onate test for truding from

ad chemically and across the we right upper bloodstained. cear like holes facing of the

o unburned or or nitrites was reas with lead

examinations graphs of Dr. ats when worn use to the Q76 we damage that ded on impact, and teeth fragt a firearm was

to identify or a Q2 rifle. The among bullets FB1. Not only ough compari-Id not, in a mathey are known

e of high veloced, did not proh any degree of is situation, the as having been

sual and microime type as the is the deformed eld caliber care the bullet porich are military-

ase was fired in hat rifle through Further, the Q467

Q12 cartridges possess no marks indicating that they had ever been loaded into the magazine of, or chambered in, the Q2 rifle or any rifle. The Q9-Q12 cartridges do possess marks indicating that they may have been loaded into disintegrating-type machinegun link belts or an eightround clip for the M1 Garand rifle.

(135) The panel finds that the Q64 bullet, the Q3 cartridge case and the Q4-Q8 cartridges are consistent in type with ammunition which would normally be contained in the 20-round Peters cartridge box. There is, however, no method of conclusively determining whether the cartridge case and the Q64 bullet were packaged by the manufacturer in the same box as the Q4-Q8 cartridges.

(136) Spectrographic and neutron activation analysis by the FBI of the Q64 bullet and the bullet portions of the Q4–Q8 cartridges conducted for purposes of elemental comparison, were inconclusive berause of variation among the bullet portions of the Q4–Q8 cartridges. (137) The panel found that the damage to the collar of the Q76 shirt, the Q77 necktie and the Q78 jacket is consistent with the damage caused by a high-velocity bullet fragmentation on impact and the resulting secondary missiles such as bone and teeth fragments. Chemical analysis revealed particles of lead throughout the damaged area of the clothing, but no gunpowder residue.

(138) The panel found no characteristic markings within the impression area of the Q71 windowsill which would either identify or eliminate the Q2 rifle as having been the cause. Chemical analysis for the presence of lead was performed on the windowsill, but the tests were negated by the lead-based paint in the impression area. Chemical analysis for the presence of gunpowder residue was performed, with argative results. The panel noted that these findings did not eliminate the possibility that a rifle was discharged at a point above or nearby windowsill.

(130) The results of the panel's microscopical examination of the Q76-Q78 clothing and the Q71 windowsill essentially correspond with these of the FBI. There is, however, no indication that the FBI had performed any chemical analysis of the Q71 windowsill.