
JEFFERSON TOWER BLDG SITE
SOUTHLAND CENTER SITE
MOTOROLA RCVR 45.78 MHZ
W.E. 111C
MOTOROLA RCVR
W.E. 111C
IFR TEL LINE
IFR TEL LINE
MOTORCYCLE RADIO
MOTOROLA MODEL T31 BAT-1130A
W/HAND-HELD MILITARY STYLE MIC, USING TRANSISTORIZED ELEMENT.
MOTOROLA TRANSMITTER
45.78 MHZ
DISPATCH CTR
106 S. HARWOOD
DISPATCH CONSOLE
SEL. SW.
COLLINS MONITOR
DISP SPKR
WESTERN ELECTRIC
TYPE 52A
(ACTIVE ISOLATION)
TEL LINE
45.78 MHZ


45.78 MHz
JEFFERSON TOWER BLDG SITE
SOUTHLAND CENTER SITE
MOTOROLA RCVR 45.78 MHz
W.E. 111C REPEAT COIL
MOTOROLA RCVR 45.78 MHz
W.E. 111C
IFR TEL LINE
IFR TEL LINE
MOTORCYCLE RADIO
MOTOROLA MODEL T31 BAT-1130A
W/HAND-HELD MILITARY STYLE MIC, USING TRANSISTORIZED ELEMENT.
MOTOROLA TRANSMITTER 45.78 MHz
DISPATCH CTR
106 S. HARWOOD
DISPATCH CONSOLE
SEL. SW.
COLLINS
DISP SPKR
WESTERN
TYPE 52A
IFR TEL LINE
45.78 MH

[redacted]

[redacted] →

Model # of Mobil Unit—

Model #

found an old Mobile Radio
of that vintage—

10:05A 9/17 Talked to [redacted]
explained to him as to what
I needed re equipment questions
said he would check to see
if he could find the data
& call me back—

[redacted] 9/19/8[illegible]

Ch. 2 = parade traffic Simple

the result to talking to 5 different people

some of the things they recall for

Sgt -

[redacted] - dispatcher

McCann

Motorola
radio Model T31 Bat - 1130A

Sample Radio Motorola
Transistorized Dispatcher Radiophone
Ser # G-26786
Transmitter type CC1500
Model T31 BAT-1130A
Motorola Inc, Chicago, Ill.

The same radio was in the two-wheeler, the three wheeler had to have some failure in the mike.

[redacted] ⑤ 9/19

quality of phones line
were better in 1963

standard mobil mike

not noise cancelling mike -
some noise cancelling circuitry

mike would have been a Motorola

Cant rn for ch 2

W.E. = western Electric

bell-
guys
over
man
hole (over)

WRR type equipment -
broadcast quality audio

[redacted]

toll grade phone lines

frequency limitation was the
recording device itself - recording
system was also a joke -
45 megahertz band was very noisy