

JLR:HPW:mar

DEC 30 1963

*report*

Mr. James J. Rowley  
Chief, United States Secret Service  
Department of the Treasury  
Washington, D. C.

Dear Mr. Rowley:

Enclosed is a copy of an inter-company communication of the Ford Motor Company dealing with changes in the President's "Bubbletop" since November 22, 1963, as described by Mr. F. Vaughn Ferguson, Ford's White House Service Instructor Representative.

In order to enable the Commission to evaluate the facts set forth in this memorandum, I would appreciate a report from the Secret Service regarding the handling of the Presidential automobile since November 22. I am particularly interested in the current condition of the windshield which was on the Presidential car at the time of the assassination.

I would also like to be advised of the existence of any statements or investigative materials relevant to your Report of December 18, 1963, other than those attached as exhibits to the Report.

Thank you for your assistance.

Sincerely,

J. Lee Rankin  
General Counsel

Enclosure