

ACCIDENT INVESTIGATOR'S REPORT
 CITY EQUIPMENT OR PRIVATELY-OWNED EQUIPMENT CITY BUSINESS

Department Police Division Patrol Employee J. D. Tippit
 Location 1000 block (West) Jefferson Date of Accident January 29, 1959 Time 8:00 p.m.

CITY VEHICLE NO. 1
 Driver J. D. Tippit Age 34 Sex M Race W
 Address 1919 Glenfield
 Vehicle 1958 Ford Sedan Damage \$ 88.00
 Year 1958 Make Ford Type Sedan
 Registration 1958 Equip. No. 63
 Est. by D. E. Mitchell Title City mechanic

PRIVATE VEHICLE NO. 2
 Driver Grady Allen Owen Age 23 Sex M Race W
 Address 929 South Oak Cliff Blvd.
 Vehicle 1951 Pontiac sedan Damage \$ 79.50
 Year 1958 Make Pontiac Type Sedan
 Registration 1958 State Texas
 Owner Forest W. Gage Number _____ State _____
 Address Dallas, Texas

Pedestrian Name None Address _____ Age _____ Sex _____ Race _____

DAMAGE TO OTHER PROPERTY

Owner None Address _____
 Property _____ Damage \$ _____

I Name None Address _____
N Age _____ Sex _____ Race _____ Driver? _____ Occupant? _____ Vehicle No. _____ Ped.? _____
J Injuries _____ Taken to _____ By _____
U _____
R Name None Address _____
E Age _____ Sex _____ Race _____ Driver? _____ Occupant? _____ Vehicle No. _____ Ped.? _____
D Injuries _____ Taken to _____ By _____


BRIEF SUMMARY OF ACCIDENT

City vehicle #1 was traveling East on Jefferson in the lane of traffic next to the South curb. Private vehicle #2 was traveling East on Jefferson in the lane of traffic next to the center parkway. Private vehicle #2 attempted to change traffic lanes and collided right front to the left front of the City vehicle #1.

IF AT INTERSECTION USE BOTH BOXES

Street <u>Jefferson</u>	Street _____
Width <u>56</u> Ft.	Width _____ Ft.
Shoulder Width <u>0</u> Ft.	Shoulder Width _____ Ft.
No. of Lanes <u>4</u>	No. of Lanes _____
Opposing Lanes Separated? <u>Yes</u>	Opposing Lanes Separated? _____
By <u>Parkway</u> Width <u>4</u> Ft.	By _____ Width _____ Ft.
One Way Street? <u>No</u>	One Way Street? _____

ACCIDENT DIAGRAM



Weather clear Type Traffic Control none
 Road Surface asphalt Road Condition dry